

Jan 27, 2021

Firmware Update Patch Notes for V2Lite 6.1.2.33.18 & 6.1.2.33.19(DHCP)

1. Updated the low temperature library and algorithms. Devices should fare better under low temperature now.
2. 6.1.2.33.19 has DHCP enabled, meaning the device will have a randomly generated IP each time it restarts; 6.1.2.33.18 does not have DHCP enabled.